

Attachment 2:
Machado Lake
Nutrient TMDL
Year 1
Wet Event 1
Monitoring Site
Photos



10_ACAD Isco auto-sampler ready for placement.




10_ACAD Isco auto sampler suspended in manhole.



10_EAST-1



10_EAST Pre storm flows



30_VERSEP Looking downstream pre storm event.




30_VERSEP Looking upstream



3I_ASHB Manhole to influent line; with double covers.



3I_ASHB View down manhole pre-storm.



3I_NORMP Looking downstream.



3I_NORMP Looking upstream.



2O_SCBG Looking upstream.



2O_SCBG Placement of auto-sampler on bridge.



2O_SCBG Auto-sampler secured to bridge.



2O_SCBG Auto-sampler on bridge with supply line to sub-straight directly below.




30_VAND Looking downstream.



30_VAND Looking upstream.




3O_VAND Isco auto-sampler secured to site fencing.



3O_VAND Auto-sampler supply tubing across pathway to channel lip.



3O_VAND Bracket holding supply tubing in place.



3O_VAND View of sieved collection end of supply tubing lying in channel bottom.